

Ikon Code

IKF00090



► Products information

Brand	Compatible Product	For Use in	OEM Ref #
Brother	Fuser Unit/Remanufactured/110v	DCP-L5502/L5602/L5652/ MFC-L5702/L5802/L5902/ HL-L5102/L5202	D008AH001

► Product Characteristics

- High Quality Fusing Unit remanufactured in Korea.
- Fusing Units are rigorously tested with both OEM/compatible Toner Cartridges and spare parts.
- Fusing Units are field tested in IKON's rental machines for more than 100,000 copies.

