

Ikon Code

IK07169



► Products information

Brand	Compatible Product	For Use in	OEM Ref #	Yield
Canon	Drum Unit Rebuild Kit/ KCMY	imageRunner Advance C5535i/C5535i II/C5535i III/C5540i/ imageRunner Advance C5540i II/C5540i III/C5550i/ imageRunner Advance C5550i II/C5550i III/C5560i/ imageRunner Advance C5560i II/C5560i III	GPR-55 Drum Unit Rebuild Kit/KCMY	/

► Product Characteristics

- High Quality Drum Unit Rebuilt kit manufactured in Japan.
- Drum Unit Rebuilt kit are rigorously tested with both OEM and compatible spare parts.
- Drum Unit Rebuilt kit are field tested in IKON's rental machines for more than 100,000 copie

