

Ikon Code

IK07170



► Products information

Brand	Compatible Product	For Use in	OEM Ref #	Yield
Canon	Drum Unit Rebuild Kit/ KCMY	imageRunner Advance DX C5840i/C5850i/C5860i/C5870i	GPR-61 Drum Unit Rebuild Kit/KCMY	/

► Product Characteristics

- High Quality Drum Unit Rebuilt kit manufactured in Japan.
- Drum Unit Rebuilt kit are rigorously tested with both OEM and compatible spare parts.
- Drum Unit Rebuilt kit are field tested in IKON's rental machines for more than 100,000 copies.

